

CIR  
CRITICAL ITEMS LIST  
FILE: CIR7/1

NAME	P/N	QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
ELECTRICAL SIGNALS HARNESS	152F0021	1	R/IRB	ELECTRICAL OPEN, +5V, +14.2V OR -14.2V LINES.	LOSS OF CONTINUITY IN +5V, +14.2V OR -14.2 LINES. (+10V PRESENTLY NOT USED).	A. DESIGN - EACH CONNECTOR/CABLE INTERFACE IS STRAIN RELIEVED BY POSITIONING THE CONDUCTORS IN PLACE. A NUMBER BACKSHELL IS THEN HELD OVER THE CONNECTOR/CABLE INTERFACE. EACH CONNECTOR/ADAPTER AT THE INTERFACE IS LOCKED IN PLACE TO PREVENT ROTATION BY A MECHANICAL LOCK AND AN ADHESIVE LOCK. NYLON AND TEFLOON COATED WIRE PROVIDES ELECTRICAL AND MECHANICAL PROPERTIES TO PREVENT BREAKAGE. THE CONDUCTORS ARE SHIELDED WITHIN A NYLON COPPER SHIELDED SHEATH WHICH CAUSES THEM TO ACT TOGETHER AND SHARE ANY LOADING PLACED ON THEM. A NYLON NYLON SHEATH IS ASSEMBLED OVER THE SHIELDED CABLES TO PROVIDE PROTECTION FROM ABRASION AND IMPACT. WIRE CRIMPING IS PER SVHS6405 (BASED ON MSFC-SPEC-Q-341).
ITEM 152 SW789152-E F10	1027-L	1	R/IRB	CAUSE: CABLE CRIMPING AGAINST CONNECTOR SHELL OR SHIELD. IMPROPER CONNECTOR SURFACE RELIEF. FAULTY CONNECTION BETWEEN THE CONNECTOR AND THE LEAD WIRES.	GFF INTERFACE: LOSS OF CHS FUNCTION. MISSION: NONE FOR SINGLE FAILURE. CIRCUIT/VEHICLE: NONE FOR SINGLE FAILURE. POSSIBLE LOSS OF GROUND WITH LOSS OF CHS, OXYGEN OR LOW VENT FLOW.	B. TEST - COMPONENT ACCEPTANCE TEST - THE 152 HARNESS IS SUBJECT TO ACCEPTANCE TESTING PER AT-EMI-152 PRIOR TO FINAL ACCEPTANCE. THIS TESTING INCLUDES THE FOLLOWING TESTS WHICH ENSURE THERE ARE NO WORKMANSHIP PROBLEMS WHICH WOULD CAUSE AN OPEN CIRCUIT ON THE +5V, +10V, +14.2V OR -14.2V LINES. CONTINUITY TESTING OF EACH CONDUCTOR AFTER COMPLETION OF HARNESS PULL TESTING (10 POUNDS) TO ENSURE THERE ARE NO OPEN CIRCUITS. THE PULL TEST IS DESIGNED TO PRE-STRESS EACH CONNECTOR/CABLE INTERFACE TO DETECT PROBLEMS WHICH WOULD CAUSE OPEN CIRCUITS.
					FVA TEST - THE +5V, 10V, -14.2V OR +14.2V LINES ARE CHECKED DURING PULL PDA TESTING PER SEMU-60-080, PARA. 35.0 TO ENSURE THERE ARE NO OPEN CIRCUITS WHICH WOULD AFFECT PULL FUNCTIONS.	C. CERTIFICATION TEST - THIS ITEM HAS COMPLETED THE STRUCTURAL VIBRATION AND SHOCK CERTIFICATION REQUIREMENTS DURING 10/81. ENGINEERING CHANGE 62006-527-2 (ADDED CONNECTOR PULL TEST) HAS BEEN UNFORWARDED AND CERTIFIED SINCE THIS CONFIGURATION HAS CERTIFIED.
						D. INSPECTION (CONTINUED) - TO ENSURE THERE ARE NO WORKMANSHIP PROBLEMS WHICH WOULD CAUSE AN OPEN CIRCUIT IN THE HARNESS CONDUCTORS, THE FOLLOWING INSPECTIONS ARE PERFORMED.

2001 ed  
100-111-728

CEL  
CRITICAL EVENTS LIST  
FILE: CEL7/1

EMU - 1172